

National Exams May 2016
98-Ind-A5, Quality Planning, Control and Assurance

Notes:

1. If doubt exists as to the interpretation of any question, the candidate is urged to submit with the answer paper, a clear statement of any assumption made.
2. This is a Closed Book examination.
3. Candidates may use one of two calculators, the Casio or Sharp approved models.
4. Candidates are permitted to bring into the examination room one aid sheet $8\frac{1}{2} \times 11$ written on both sides.
5. Any five questions constitute a complete paper. Only the first five questions as they appear in your answer book will be marked.
6. All questions are of equal value.
7. Relevant statistical tables are attached.

Question 1 (20 marks)

- 5 a) Describe briefly the purpose of a quality plan and discuss the differences among the strategic, tactical and operational quality planning.
- 5 b) Summarize the key elements of TQM. What is the difference between the traditional TQC and modern TQM? What is a quality circle?
- 5 c) Explain the difference between Taguchi's definition of quality and the traditional definition and the corresponding loss functions. How would you summarize Taguchi's approach to quality improvement?
- 5 d) What is the purpose of quality certification and prizes in quality? Describe briefly the structure of ISO 9000.

Question 2 (20 marks)

- 6 a) Explain how the traditional control charts can be used to control "trend" process such as "tool-wear" processes. Explain the difference between the engineering process control and SPC. EWMA chart is frequently used in industry for both EPC and SPC. Explain the rationale for using EWMA for both types of control.
- 7 b) Samples of $n=4$ units are taken from a process every hour. The \bar{X} and R values for a particular quality characteristic are determined. After 30 samples have been collected, we calculate $\bar{\bar{X}} = 20$ and $\bar{R} = 4.56$. Find the 3 sigma control limits for both \bar{X} and R charts. Estimate the process mean and standard deviation. If the process mean shifts to 25, what is the probability of not detecting this shift on the two subsequent samples following the shift?
- 7 c) Consider the data in 2b). To control future production, find the minimum sample size n for the \bar{X} chart such that when the process mean shifts from the in-control value to 23, the average run length is less than or equal to 4.

Question 3 (20 marks)

- 5 a) Draw a typical product life cycle curve and explain the three phases in the evolution of a product failure rate.
Describe the probability distributions used to model the three phases.
- 5 b) Provide the definitions of the reliability function, density function, failure rate and the mean time to failure and show the formulas for the exponential distribution. Explain the meaning of the memoryless property of the exponential.
- 10 c) The specimens of a new electric insulation are life tested. The failure times in hours are as follows:
303, 467, 961, 1153, 175, 521, 617, 713, 665, 685
Plot the data on the attached Weibull paper and estimate the shape parameter, the characteristic life, and the mean time to failure.

Question 4 (20 marks)

- 5 a) Explain why two control charts are used for variable data and only one chart for attribute data. What is the difference between p chart and np chart, c chart and u chart?
 Explain why in a real situation, an inspection unit is frequently defined as several physical units, for example 1 inspection unit may consist of 4 parts.
- 6 b) Assume that for a p chart, the lower control limit is zero and the proportion of defectives in a sample is zero. When would you stop the process and search for an assignable cause and when you would not? Explain.
- 9 c) The number of workmanship nonconformities observed in the final inspection of disk-drive assemblies has been tabulated as shown below. Set up the appropriate control chart with 3 sigma limits. Revise, if necessary. Estimate the in-control mean number of nonconformities per assembly.

Day	1	2	3	4	5	6	7	8	9	10
No. of assemblies inspected	1	3	2	4	2	1	3	4	2	4
Total No. of nonconformities	8	21	10	30	18	10	20	24	15	26

Question 5 (20 marks)

- 5 a) Describe the three stages in the product and process design: system design, parameter design and the tolerance design. What is the role of the quality function deployment in the product design and in which stage is it applied?
- 5 b) Provide a brief description and usage of the Taguchi Methods. Explain the following: signal-to-noise ratio; inner and outer array, linear graph, graph of marginal averages. Discuss the limitations of the Taguchi Methods.
 Give examples of robust design for a product and a manufacturing process.
- 10 c) An automobile engineer wishes to study the effect of speed on the quantity of carbon monoxide emissions. Although attention will be fixed upon a single make of automobile travelling at different speeds, it is known that the external temperature has an effect. The tests are run at 15, 20 and 25 mph, the blocks being determined by the external temperatures of 20°F, 40°F and 60°F. The table below contains the emission test data (in grams per vehicle mile).

Mph	Temperature (°F)		
	20°	40°	60°
15	104	92	78
20	88	70	62
25	70	56	50

Is there an indication that speed has an effect on the emission? Is there an indication of the block effect? Formulate and test the appropriate hypotheses, both at $\alpha = 0.05$ level of significance.


Question 6 (20 marks)

- 6 a) What is the purpose of acceptance sampling? Explain the difference between the acceptance sampling by variables and by attributes. Compare MIL-STD-105E and MIL-STD-414. They are both AQL-based. Explain what this means.
- 6 b) Describe briefly the two types of the Dodge-Romig sampling plans: LTPD and AOQL plans. Compare with the AQL-based plans.
- 8 c) Items are submitted for inspection using MIL-STD-105E in lots of size 400. The required AQL is 1%. Consider normal inspection and general inspection level II. Find a single sampling plan using MIL-STD-105E. Calculate the producer's and consumer's risk for the selected sampling plan if LQL is equal to 5%.

A-6 APPENDIX

Appendix II Cumulative Standard Normal Distribution

$$\Phi(z) = \int_{-\infty}^z \frac{1}{\sqrt{2\pi}} e^{-u^2/2} du$$



z	0.00	0.01	0.02	0.03	0.04	z
0.0	0.50000	0.50399	0.50798	0.51197	0.51595	0.0
0.1	0.53983	0.54379	0.54776	0.55172	0.55567	0.1
0.2	0.57926	0.58317	0.58706	0.59095	0.59483	0.2
0.3	0.61791	0.62172	0.62551	0.62930	0.63307	0.3
0.4	0.65542	0.65910	0.66276	0.66640	0.67003	0.4
0.5	0.69146	0.69497	0.69847	0.70194	0.70540	0.5
0.6	0.72575	0.72907	0.73237	0.73565	0.73891	0.6
0.7	0.75803	0.76115	0.76424	0.76730	0.77035	0.7
0.8	0.78814	0.79103	0.79389	0.79673	0.79954	0.8
0.9	0.81594	0.81859	0.82121	0.82381	0.82639	0.9
1.0	0.84134	0.84375	0.84613	0.84849	0.85083	1.0
1.1	0.86433	0.86650	0.86864	0.87076	0.87285	1.1
1.2	0.88493	0.88686	0.88877	0.89065	0.89251	1.2
1.3	0.90320	0.90490	0.90658	0.90824	0.90988	1.3
1.4	0.91924	0.92073	0.92219	0.92364	0.92506	1.4
1.5	0.93319	0.93448	0.93574	0.93699	0.93822	1.5
1.6	0.94520	0.94630	0.94738	0.94845	0.94950	1.6
1.7	0.95543	0.95637	0.95728	0.95818	0.95907	1.7
1.8	0.96407	0.96485	0.96562	0.96637	0.96711	1.8
1.9	0.97128	0.97193	0.97257	0.97320	0.97381	1.9
2.0	0.97725	0.97778	0.97831	0.97882	0.97932	2.0
2.1	0.98214	0.98257	0.98300	0.98341	0.98382	2.1
2.2	0.98610	0.98645	0.98679	0.98713	0.98745	2.2
2.3	0.98928	0.98956	0.98983	0.99010	0.99036	2.3
2.4	0.99180	0.99202	0.99224	0.99245	0.99266	2.4
2.5	0.99379	0.99396	0.99413	0.99430	0.99446	2.5
2.6	0.99534	0.99547	0.99560	0.99573	0.99585	2.6
2.7	0.99653	0.99664	0.99674	0.99683	0.99693	2.7
2.8	0.99744	0.99752	0.99760	0.99767	0.99774	2.8
2.9	0.99813	0.99819	0.99825	0.99831	0.99836	2.9
3.0	0.99865	0.99869	0.99874	0.99878	0.99882	3.0
3.1	0.99903	0.99906	0.99910	0.99913	0.99916	3.1
3.2	0.99931	0.99934	0.99936	0.99938	0.99940	3.2
3.3	0.99952	0.99953	0.99955	0.99957	0.99958	3.3
3.4	0.99966	0.99968	0.99969	0.99970	0.99971	3.4
3.5	0.99977	0.99978	0.99978	0.99979	0.99980	3.5
3.6	0.99984	0.99985	0.99985	0.99986	0.99986	3.6
3.7	0.99989	0.99990	0.99990	0.99990	0.99991	3.7
3.8	0.99993	0.99993	0.99993	0.99994	0.99994	3.8
3.9	0.99995	0.99995	0.99996	0.99996	0.99996	3.9

Appendix II (Continued)

$$\Phi(z) = \int_{-\infty}^z \frac{1}{\sqrt{2\pi}} e^{-u^2/2} du$$

<i>z</i>	0.05	0.06	0.07	0.08	0.09	<i>z</i>
0.0	0.51994	0.52392	0.52790	0.53188	0.53586	0.0
0.1	0.55962	0.56356	0.56749	0.57142	0.57534	0.1
0.2	0.59871	0.60257	0.60642	0.61026	0.61409	0.2
0.3	0.63683	0.64058	0.64431	0.64803	0.65173	0.3
0.4	0.67364	0.67724	0.68082	0.68438	0.68793	0.4
0.5	0.70884	0.71226	0.71566	0.71904	0.72240	0.5
0.6	0.74215	0.74537	0.74857	0.75175	0.75490	0.6
0.7	0.77337	0.77637	0.77935	0.78230	0.78523	0.7
0.8	0.80234	0.80510	0.80785	0.81057	0.81327	0.8
0.9	0.82894	0.83147	0.83397	0.83646	0.83891	0.9
1.0	0.85314	0.85543	0.85769	0.85993	0.86214	1.0
1.1	0.87493	0.87697	0.87900	0.88100	0.88297	1.1
1.2	0.89435	0.89616	0.89796	0.89973	0.90147	1.2
1.3	0.91149	0.91308	0.91465	0.91621	0.91773	1.3
1.4	0.92647	0.92785	0.92922	0.93056	0.93189	1.4
1.5	0.93943	0.94062	0.94179	0.94295	0.94408	1.5
1.6	0.95053	0.95154	0.95254	0.95352	0.95448	1.6
1.7	0.95994	0.96080	0.96164	0.96246	0.96327	1.7
1.8	0.96784	0.96856	0.96926	0.96995	0.97062	1.8
1.9	0.97441	0.97500	0.97558	0.97615	0.97670	1.9
2.0	0.97982	0.98030	0.98077	0.98124	0.98169	2.0
2.1	0.98422	0.98461	0.98500	0.98537	0.98574	2.1
2.2	0.98778	0.98809	0.98840	0.98870	0.98899	2.2
2.3	0.99061	0.99086	0.99111	0.99134	0.99158	2.3
2.4	0.99286	0.99305	0.99324	0.99343	0.99361	2.4
2.5	0.99461	0.99477	0.99492	0.99506	0.99520	2.5
2.6	0.99598	0.99609	0.99621	0.99632	0.99643	2.6
2.7	0.99702	0.99711	0.99720	0.99728	0.99736	2.7
2.8	0.99781	0.99788	0.99795	0.99801	0.99807	2.8
2.9	0.99841	0.99846	0.99851	0.99856	0.99861	2.9
3.0	0.99886	0.99889	0.99893	0.99897	0.99900	3.0
3.1	0.99918	0.99921	0.99924	0.99926	0.99929	3.1
3.2	0.99942	0.99944	0.99946	0.99948	0.99950	3.2
3.3	0.99960	0.99961	0.99962	0.99964	0.99965	3.3
3.4	0.99972	0.99973	0.99974	0.99975	0.99976	3.4
3.5	0.99981	0.99981	0.99982	0.99983	0.99983	3.5
3.6	0.99987	0.99987	0.99988	0.99988	0.99989	3.6
3.7	0.99991	0.99992	0.99992	0.99992	0.99992	3.7
3.8	0.99994	0.99994	0.99995	0.99995	0.99995	3.8
3.9	0.99996	0.99996	0.99996	0.99997	0.99997	3.9

Appendix VI Factors for Constructing Variables Control Charts

Observations in Sample, n	Chart for Averages						Chart for Standard Deviations									
	Factors for Control Limits			Factors for Center Line			Factors for Control Limits			Factors for Control Limits						
	A_1	A_2	A_3	C_1	$1/C_1$	B_1	B_2	B_3	B_4	d_2	$1/d_2$	d_4	D_1	D_2	D_3	D_4
2	2.121	1.880	2.659	0.7979	1.2533	0	3.267	0	2.606	1.128	0.8865	0.353	0	3.686	0	3.267
3	1.7332	1.0223	1.954	0.8862	1.1284	0	2.568	0	2.276	1.693	0.5907	0.888	0	4.358	0	2.575
4	1.500	0.729	1.628	0.9213	1.0854	0	2.266	0	2.059	0.4857	0.380	0	4.698	0	2.282	
5	1.342	0.577	1.427	0.9400	1.0638	0	2.089	0	1.964	2.326	0.4299	0.854	0	4.918	0	2.115
6	1.2225	0.483	1.287	0.9515	1.0510	0.030	1.970	0.029	1.874	2.534	0.3946	0.848	0	5.078	0	2.004
7	1.134	0.419	1.182	0.9594	1.0423	0.118	1.882	0.113	1.806	2.704	0.3698	0.833	0.204	5.204	0.076	1.924
8	1.061	0.373	1.099	0.9650	1.0363	0.185	1.815	0.179	1.751	2.847	0.3512	0.820	0.388	5.306	0.136	1.864
9	1.000	0.337	1.032	0.9693	1.0317	0.239	1.761	0.232	1.707	2.970	0.3367	0.808	0.547	5.393	0.184	1.816
10	0.949	0.308	0.975	0.9727	1.0281	0.284	1.716	0.276	1.669	3.078	0.3249	0.797	0.687	5.469	0.223	1.777
11	0.905	0.285	0.927	0.9754	1.0252	0.321	1.679	0.313	1.637	3.173	0.3152	0.787	0.811	5.535	0.256	1.744
12	0.866	0.266	0.886	0.9776	1.0229	0.354	1.645	0.346	1.610	3.258	0.3069	0.778	0.922	5.594	0.283	1.717
13	0.832	0.249	0.850	0.9794	1.0210	0.382	1.618	0.374	1.585	3.336	0.2998	0.770	1.025	5.647	0.307	1.693
14	0.802	0.235	0.817	0.9810	1.0194	0.406	1.594	0.399	1.563	3.407	0.2935	0.763	1.118	5.696	0.328	1.672
15	0.775	0.223	0.789	0.9823	1.0180	0.428	1.572	0.421	1.544	3.472	0.2880	0.756	1.203	5.741	0.347	1.653
16	0.750	0.212	0.763	0.9835	1.0163	0.448	1.552	0.440	1.526	3.532	0.2831	0.750	1.282	5.782	0.363	1.637
17	0.723	0.203	0.739	0.9845	1.0157	0.466	1.534	0.458	1.511	3.588	0.2787	0.744	1.356	5.820	0.378	1.622
18	0.707	0.194	0.718	0.9854	1.0148	0.482	1.518	0.475	1.496	3.640	0.2747	0.739	1.424	5.856	0.391	1.608
19	0.688	0.187	0.698	0.9862	1.0140	0.497	1.503	0.490	1.483	3.689	0.2711	0.734	1.487	5.891	0.403	1.597
20	0.671	0.180	0.680	0.9869	1.0133	0.510	1.490	0.504	1.470	3.735	0.2677	0.729	1.549	5.921	0.415	1.585
21	0.655	0.173	0.663	0.9876	1.0126	0.523	1.477	0.516	1.459	3.778	0.2647	0.724	1.605	5.951	0.425	1.575
22	0.640	0.167	0.647	0.9882	1.0119	0.534	1.466	0.528	1.448	3.819	0.2618	0.720	1.659	5.979	0.434	1.566
23	0.626	0.162	0.633	0.9887	1.0114	0.545	1.455	0.539	1.438	3.858	0.2592	0.716	1.710	6.006	0.443	1.557
24	0.612	0.157	0.619	0.9892	1.0109	0.555	1.445	0.549	1.429	3.895	0.2567	0.712	1.759	6.031	0.451	1.548
25	0.600	0.153	0.606	0.9896	1.0105	0.565	1.435	0.559	1.420	3.931	0.2544	0.708	1.806	6.056	0.459	1.541

For $n > 25$

$$A = \frac{3}{\sqrt{n}}, \quad A_3 = \frac{3}{C_4 \sqrt{n}}, \quad C_4 = \frac{4(n-1)}{4n-3},$$

$$B_2 = 1 - \frac{3}{C_4 \sqrt{2(n-1)}}, \quad B_4 = 1 + \frac{3}{C_4 \sqrt{2(n-1)}},$$

$$B_3 = C_4 - \frac{3}{\sqrt{2(n-1)}}, \quad B_6 = C_4 + \frac{3}{\sqrt{2(n-1)}}.$$

Appendix V (Continued)

v_2	v_1	Degrees of freedom for the numerator (v_1)												$F_{0.05, v_1, v_2}$
		1	2	3	4	5	6	7	8	9	10	12	15	
1	161.4	199.5	215.7	224.6	230.2	234.0	236.8	238.9	240.5	241.9	243.9	245.9	248.0	249.1
2	18.51	19.00	19.16	19.25	19.30	19.35	19.37	19.38	19.40	19.41	19.43	19.45	19.46	19.47
3	10.13	9.55	9.28	9.12	9.01	8.94	8.89	8.85	8.81	8.79	8.74	8.70	8.66	8.64
4	7.71	6.94	6.59	6.39	6.26	6.16	6.09	6.04	6.00	5.96	5.91	5.86	5.80	5.77
5	6.61	5.79	5.41	5.19	5.05	4.95	4.88	4.82	4.77	4.74	4.68	4.62	4.56	4.52
6	5.59	5.14	4.76	4.53	4.39	4.28	4.21	4.15	4.10	4.06	4.00	3.94	3.87	3.84
7	5.59	4.74	4.35	4.12	3.97	3.87	3.79	3.73	3.68	3.64	3.57	3.51	3.44	3.41
8	5.32	4.46	4.07	3.84	3.69	3.58	3.50	3.44	3.39	3.35	3.28	3.22	3.15	3.12
9	5.12	4.26	3.86	3.63	3.48	3.37	3.29	3.23	3.18	3.14	3.07	3.01	2.94	2.90
10	4.96	4.10	3.71	3.48	3.33	3.22	3.14	3.07	3.02	2.98	2.91	2.85	2.77	2.74
11	4.84	3.98	3.59	3.36	3.20	3.09	3.01	2.95	2.90	2.85	2.79	2.72	2.65	2.61
12	4.75	3.89	3.49	3.26	3.11	3.00	2.91	2.85	2.80	2.75	2.69	2.62	2.54	2.51
13	4.67	3.81	3.41	3.18	3.03	2.92	2.83	2.77	2.71	2.67	2.60	2.53	2.46	2.42
14	4.60	3.74	3.34	3.11	2.96	2.85	2.76	2.70	2.65	2.60	2.53	2.46	2.39	2.35
15	4.54	3.68	3.29	3.06	2.90	2.79	2.71	2.64	2.59	2.54	2.48	2.40	2.35	2.31
16	4.49	3.63	3.24	3.01	2.85	2.74	2.66	2.59	2.54	2.49	2.42	2.35	2.28	2.24
17	4.45	3.59	3.20	2.96	2.81	2.79	2.61	2.55	2.49	2.45	2.38	2.31	2.23	2.19
18	4.41	3.55	3.16	2.93	2.77	2.66	2.58	2.51	2.46	2.41	2.34	2.27	2.19	2.15
19	4.38	3.52	3.13	2.90	2.74	2.63	2.54	2.48	2.42	2.38	2.31	2.23	2.16	2.11
20	4.35	3.49	3.10	2.87	2.71	2.60	2.51	2.45	2.39	2.35	2.28	2.20	2.12	2.08
21	4.32	3.47	3.07	2.84	2.68	2.57	2.49	2.42	2.37	2.32	2.25	2.18	2.10	2.05
22	4.30	3.44	3.05	2.82	2.66	2.55	2.46	2.40	2.34	2.30	2.23	2.15	2.07	2.01
23	4.28	3.42	3.03	2.80	2.64	2.53	2.44	2.37	2.32	2.27	2.20	2.13	2.05	2.00
24	4.26	3.40	3.01	2.78	2.62	2.51	2.42	2.36	2.30	2.25	2.18	2.11	2.06	2.02
25	4.24	3.39	2.99	2.76	2.60	2.49	2.40	2.34	2.28	2.24	2.16	2.09	2.03	1.98
26	4.23	3.37	2.98	2.74	2.59	2.47	2.39	2.32	2.27	2.22	2.15	2.07	1.99	1.95
27	4.21	3.35	2.96	2.73	2.57	2.46	2.37	2.31	2.25	2.20	2.13	2.06	1.97	1.93
28	4.20	3.34	2.95	2.71	2.56	2.45	2.36	2.29	2.24	2.19	2.12	2.04	1.96	1.91
29	4.18	3.33	2.93	2.70	2.55	2.43	2.35	2.28	2.22	2.18	2.10	2.03	1.94	1.87
30	4.17	3.32	2.92	2.69	2.53	2.42	2.33	2.27	2.21	2.16	2.09	2.01	1.93	1.84
31	4.08	3.23	2.84	2.61	2.45	2.34	2.25	2.18	2.12	2.08	2.00	1.92	1.84	1.77
32	4.00	3.15	2.76	2.53	2.37	2.25	2.17	2.10	2.04	1.99	1.92	1.84	1.75	1.69
33	3.92	3.07	2.68	2.45	2.29	2.17	2.09	2.02	1.96	1.91	1.83	1.75	1.65	1.59
34	3.84	3.00	2.60	2.37	2.21	2.10	2.01	1.94	1.88	1.83	1.75	1.67	1.57	1.52

Degrees of freedom for the denominator (v_2)Note: $F_{0.05, v_1, v_2} = 1/F_{v_2, 0.05, v_1}$.

WEIBULL PROBABILITY CHART

◎ Estimation Point




Table 14-4 Sample Size Code Letters (MIL STD 105E, Table 1)

Lot or Batch Size	Special Inspection Levels				General Inspection Levels		
	S-1	S-2	S-3	S-4	I	II	III
2 to 8	A	A	A	A	A	A	B
9 to 15	A	A	A	A	A	B	C
16 to 25	A	A	B	B	B	C	D
26 to 50	A	B	B	C	C	D	E
51 to 90	B	B	C	C	C	E	F
91 to 150	B	B	C	D	D	F	G
151 to 280	B	C	D	E	E	G	H
281 to 500	B	C	D	E	F	H	J
501 to 1200	C	C	E	F	G	J	K
1201 to 3200	C	D	E	G	H	K	L
3201 to 10000	C	D	F	G	J	L	M
10001 to 35000	C	D	F	H	K	M	N
35001 to 150000	D	E	G	J	L	N	P
150001 to 500000	D	E	G	J	M	P	Q
500001 and over	D	E	H	K	N	Q	R

Table 13.5 Master Table for Normal Inspection—Single Sampling (MIL-STD 105E, Table II.A)

Sample size	Sample code letter	Acceptable Quality Levels (Normal Inspection)																																		
		0.010	0.015	0.025	0.040	0.065	0.10	0.15	0.25	0.40	0.65	1.0	1.5	2.5	4.0	6.5	10	15	25	40	65	100	150	220	400	650	1000									
A	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	6	7	8	10	11	14	15	21	22	30	31
B	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31
C	5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
D	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
E	13	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
F	20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
G	32	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
H	50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
J	80	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
K	125	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
L	200	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
M	315	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
N	500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
P	800	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
Q	1250	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
R	2000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
S	3300	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
T	5000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
U	8000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
V	12500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
W	20000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
X	33000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
Y	50000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	
Z	80000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	30	31	

= Use first sampling plan above arrow.

R_e = Reception number.

R_e = Reception number.